| USN | | | | | 100 | 10M | AA54 |
|------|--|--|--|--|-----|-----|------|
| USIN | | | | | | | |

Fifth Semester B.E. Degree Examination, Dec.2017/Jan.2018

| | | Manufacturing Process - III | an.2016 | | | | | | | | | | |
|---|----------------|---|--------------------------|--|--|--|--|--|--|--|--|--|--|
| | | Manufacturing Process - III | | | | | | | | | | | |
| Tim | Max. Marks:100 | | | | | | | | | | | | |
| Note: Answer any FIVE full questions, selecting atleast TWO questions from each part. | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | PART - A | > | | | | | | | | | | |
| 1 | a. | Give the broad classification of metal working process. List the advan- | - | | | | | | | | | | |
| | h | of metal working processes. Describe the characteristics of wrought products. | (10 Marks) | | | | | | | | | | |
| | c. | | (04 Marks) (06 Marks) | | | | | | | | | | |
| | ٠. | Explain Flesca and Vol. Indees yield effectua. | (00 Marks) | | | | | | | | | | |
| 2 | a. | What is Deformation zone geometry? Explain the concept of true st | ress and true strain. | | | | | | | | | | |
| | | | (10 Marks) | | | | | | | | | | |
| | b. | Write a note on the effect of following parameters during metal working | | | | | | | | | | | |
| | | i) Temperature ii) Friction iii) Strain rate iv) Residual | | | | | | | | | | | |
| | | v) Lubrication. | (10 Marks) | | | | | | | | | | |
| 3 | 0 | Classify foreing processes I in the defeate in factors | (40 %# 1) | | | | | | | | | | |
| 3 | a. b | Classify forging processes. List the defects in forging Derive an expression for forging pressure and load in open die forging. | (10 Marks) | | | | | | | | | | |
| | υ. | Derive an expression for forging pressure and load in open the forging. | (10 Marks) | | | | | | | | | | |
| 4 | a. | List and explain different types of roll mills. | (10 Marks) | | | | | | | | | | |
| | | Derive an expression for rolling load. | (06 Marks) | | | | | | | | | | |
| | c. | List the defects in rolled products. | (04 Marks) | | | | | | | | | | |
| | | | | | | | | | | | | | |
| _ | | PART - B | | | | | | | | | | | |
| 5 | a. | r | | | | | | | | | | | |
| | l _a | by slab analysis method. | (10 Marks) | | | | | | | | | | |
| | υ. | What are the different types of extrusion processes? With the help of seamless tube extrusion. | | | | | | | | | | | |
| | | scarness tube extrusion. | (10 Marks) | | | | | | | | | | |
| 6 | a. | Sketch and explain progressive die and open back inclined press in | sheet metal forming. | | | | | | | | | | |
| | | (%) | (10 Marks) | | | | | | | | | | |
| | b. | Differentiate between Piercing and Blanking. Sketch and explain rubbe | r forming. (10 Marks) | | | | | | | | | | |
| - | | | C | | | | | | | | | | |
| 7 | a. | 8 1 | 1/// | | | | | | | | | | |
| | b. | products. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | (10 Marks) | | | | | | | | | | |
| | c. | | (06 Marks) | | | | | | | | | | |
| | ٠. | 2.2.2 The state of the sta | () marks) | | | | | | | | | | |
| 8 | a. | With the help of flow chart, explain the steps involved in making pow | der metallurgy parts. | | | | | | | | | | |

- (08 Marks)
 - b. Explain the different methods used for the production of metal powders in powder metallurgy. (08 Marks)
 - c. List the application of powder metallurgy components. (04 Marks)