Important Note: 1. On completing your answers, compulsorily draw diagonal cross lines on the remaining blank pages. 2. Any revealing of identification, appeal to evaluator and /or equations written eg, 42+8 = 50, will be treated as malpractice.

and Threshold.

b. Define Error. Give the detailed classification of errors.

GBCS SCHEME

Third Semester B.E. Degree Examination, June/July 2018 Measurement and Metrology Time: 3 hrs. ' Max. Marks: 80 Note: Answer any FIVE full questions, choosing one full question from each module. Module-1 1 a. Define Metrology and state its objectives. (04 Marks) b. Discuss briefly Line standard and End standard. (06 Marks) c. Describe the phenomena of wringing of slip gauges, with neat sketch. (06 Marks) b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49,3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , Tr ₈ = 10i and 176 grade the tolerance magnitude is multiplied by 10 at each fifth step. (08 Marks) b. Explain Hole basis system and Shaft basis system. Which is preferred and why? (06 Marks) c. Write a note on interchangeability and selective assembly. (04 Marks) Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. (08 Marks) b. Explain the principle of working of sine bar and sine centre, with sketches. (08 Marks) b. Explain the principle of working of sine bar and sine centre, with sketches. (08 Marks) b. With a neat sketch, explain the construction of working of LVDT. (08 Marks) Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)					
Time: 3 hrs. ' Max. Marks: 80 Note: Answer any FIVE full questions, choosing one full question from each module. Module-1	USN			15AE36	
Note: Answer any FIVE full questions, choosing one full question from each module. Module-1			Third Semester B.E. Degree Examination, June/July 2013	8	
Note: Answer any FIVE full questions, choosing one full question from each module. Module-1			Measurement and Metrology		
Note: Answer any FIVE full questions, choosing one full question from each module. Module-1					
Module-1 1 a. Define Metrology and state its objectives. b. Discuss briefly Line standard and End standard. c. Describe the phenomena of wringing of slip gauges, with neat sketch. OR 2 a. Describe with sketch, Imperial standard yard and International prototype meter. b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49.3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT _e = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	Tin	ne: í	hrs. Max. M	Marks: 80	
1 a. Define Metrology and state its objectives. b. Discuss briefly Line standard and End standard. c. Describe the phenomena of wringing of slip gauges, with neat sketch. OR 2 a. Describe with sketch, Imperial standard yard and International prototype meter. b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49.3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. OR 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)		N	ote: Answer any FIVE full questions, choosing one full question from each mo	odule.	
1 a. Define Metrology and state its objectives. b. Discuss briefly Line standard and End standard. c. Describe the phenomena of wringing of slip gauges, with neat sketch. OR 2 a. Describe with sketch, Imperial standard yard and International prototype meter. b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49.3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. OR 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)			Module-1		
OR 2 a. Describe with sketch, Imperial standard yard and International prototype meter. (08 Marks) b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49,3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. (08 Marks) Module-2 3 a. Define Fit. Explain different types of Fits with sketches. (08 Marks) b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ ds. The following assumptions are made: 50mm ties in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} . IT ₆ = 10i and IT ₆ grade the tolerance magnitude is multiplied by 10 at each fifth step. (08 Marks) OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. (06 Marks) b. Explain Hole basis system and Shaft basis system. Which is preferred and why? (06 Marks) c. Write a note on interchangeability and selective assembly (04 Marks) b. Explain the principle of working of sine bar and sine centre, with sketches. (08 Marks) OR 6 a. How do you find effective diameter of a screw thread using two – wire method? (08 Marks) b. With a neat sketch, explain the construction of working of LVDT. (08 Marks)	1	a.		(04 Marks)	
OR 2 a. Describe with sketch, Imperial standard yard and International prototype meter. (08 Marks) b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49.3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ ds. The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} . IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)		b.		(06 Marks)	
2 a. Describe with sketch, Imperial standard yard and International prototype meter. b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49.3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. Discuss with block diagram of generalized measurement system. Module-4 7 a. Discuss with block diagram of generalized measurement system.		c.	Describe the phenomena of wringing of slip gauges, with neat sketch.	(06 Marks)	
2 a. Describe with sketch, Imperial standard yard and International prototype meter. b. Give the details of M112 set of slip gauges and build the following dimensions: i) 49.3115 mm ii) 78.3665 mm iii) 35.4875mm. Using 2 protector slip of 2.5mm each. Module-2 3 a. Define Fit. Explain different types of Fits with sketches. b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. How do you find effective diameter of a screw thread using two – wire method? OR 6 a. Discuss with block diagram of generalized measurement system. Module-4 7 a. Discuss with block diagram of generalized measurement system.			OR		
Module-2 3 a. Define Fit. Explain different types of Fits with sketches. b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	2		Describe with sketch, Imperial standard yard and International prototype meter. Give the details of M112 set of slip gauges and build the following dimensions:		
Module-2 3 a. Define Fit. Explain different types of Fits with sketches. b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)				-	
 a. Define Fit. Explain different types of Fits with sketches. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H₇d₈. The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D^{0.44}, IT₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. (06 Marks) (08 Marks) Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks) 		<	each.	(08 Marks)	
 a. Define Fit. Explain different types of Fits with sketches. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H₇d₈. The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D^{0.44}, IT₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. (06 Marks) (08 Marks) Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks) 	,	The state of the s	Module-2	~ (S)°	
b. Calculate the dimensions of plug gauges and ring gauges to control the production of 50mm shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} , IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. (06 Marks) (06 Marks) (08 Marks) Module-3 b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	3	(a)	. 마스트 : 마스트 : 1888 : 1	(08 Marks)	
shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diameter step of 30-50mm. The upper deviation for the shaft is given by -16D ^{0.44} . IT ₆ = 10i and IT6 grade the tolerance magnitude is multiplied by 10 at each fifth step. OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	2 TE) 그 이 이 그 그 사이에 이 그 사이를 하는 것이 되었다면 하게 되었다면 하는 것이 되었다면 그 그 그 사이를 하는데 되었다면 하는데 하는데 하는데 나는데 그는데 그 사이를 하는데 하는데 그 사이를 하는데 되었다면 하는데 그 사이를 하는데 하는데 그는데 그 사이를 하는데 하는데 그는데 그는데 그는데 그는데 그는데 그는데 그 사이를 하는데 그는데 그는데 그는데 그는데 그는데 그는데 그는데 그는데 그는데 그	N. O. J. A.	
OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks) (08 Marks)			shaft and Hole pair H ₇ d ₈ . The following assumptions are made: 50mm lies in a diam		
OR 4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (06 Marks) (08 Marks)			step of 30-50mm. The upper deviation for the shaft is given by $-16D^{0.44}$. IT ₆ =	10i and IT6	
4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. (06 Marks) (06 Marks) (04 Marks) Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)			grade the tolerance magnitude is multiplied by 10 at each fifth step.	(08 Marks)	
4 a. What are Limit gauges? Sketch and explain plain plug gauges. b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. (06 Marks) (06 Marks) (04 Marks) Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)			OP		
b. Explain Hole basis system and Shaft basis system. Which is preferred and why? c. Write a note on interchangeability and selective assembly. Module-3 5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. OR 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	4	а		(06 Marks)	
c. Write a note on interchangeability and selective assembly. Module-3 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. How do you find effective diameter of a screw thread using two – wire method? With a neat sketch, explain the construction of working of LVDT. Module-4 Discuss with block diagram of generalized measurement system. (04 Marks) (08 Marks)					
5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks) (08 Marks)					
5 a. Define Comparators. Give the classification and characteristics of comparators. b. Explain the principle of working of sine bar and sine centre, with sketches. 6 a. How do you find effective diameter of a screw thread using two – wire method? b. With a neat sketch, explain the construction of working of LVDT. Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks) (08 Marks)					
b. Explain the principle of working of sine bar and sine centre, with sketches. (08 Marks) 6 a. How do you find effective diameter of a screw thread using two – wire method? (08 Marks) b. With a neat sketch, explain the construction of working of LVDT. (08 Marks) Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)					
6 a. How do you find effective diameter of a screw thread using two – wire method? (08 Marks) b. With a neat sketch, explain the construction of working of LVDT. (08 Marks) Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	5				
6 a. How do you find effective diameter of a screw thread using two – wire method? (08 Marks) b. With a neat sketch, explain the construction of working of LVDT. (08 Marks) Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)		b.	Explain the principle of working of sine bar and sine centre, with sketches.	(08 Marks)	
6 a. How do you find effective diameter of a screw thread using two – wire method? (08 Marks) b. With a neat sketch, explain the construction of working of LVDT. (08 Marks) Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)					
b. With a neat sketch, explain the construction of working of LVDT. (08 Marks) Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	6	0		(08 Marks)	
Module-4 7 a. Discuss with block diagram of generalized measurement system. (08 Marks)	U				
7 a. Discuss with block diagram of generalized measurement system. (08 Marks)		U.	With a heat sketch, explain the construction of working of 2 v 2 v.	(00 1141143)	
			Module-4		
	7	a.	Discuss with block diagram of generalized measurement system.	(08 Marks)	
		b.	Explain the following pressure sensitive elements with sketches:		
i) Bourdon tubes iii) Bellows iii) Diaphragms. (08 Marks)			i) Bourdon tubes iii) Bellows iii) Diaphragms.	(08 Marks)	
OD			OD		
8 a. Explain the following:	0	0			
8 a. Explain the following: i) Accuracy and Precision ii) Repeatability and Reproducibility iii) Resolution	0	a.		Resolution	

(08 Marks)

(08 Marks)

15AE36

Module 5

Explain with sketch, Mechanical - Dynamometer. (08 Marks) What is Pyrometer? Explain the working of Optical Pyrometer. (08 Marks)

OR

State and explain laws of thermocouples. Describe with sketch, Mcleod gauge. 10 a.

(08 Marks) (08 Marks)