## CRCS SCHEME

								UL		0		للل		l d	7			
1							T		T									15AU32
		Th	ird	Sei	ne	ster	RF	' D	ear	00 F	van	nine	ation	Do	o 20	1 Q / T.	an.201	10
		1 11	II U	SCI								18	W. A.				a11.201	19
					IAI	ate	IIa		CIC	<b>#11C</b>	e a	ПС	IAIE	tai	lurg	IJ		
16	: 3	hrs.									_^	>				A I	Max. M	Iarks: 80
	<b>N</b> T		,							-	- N					1		
	N	ote: 2	4nsu	ver a	iny	FIVE	full	que	estion	s, ch	oosin	<b>g O</b> /	VE fu	ll que	stion	from (	each mo	dule.
										1	Iodul	e_1			4			
2	ι.	Defi	ne S	pace	lat	tice. F	ind o	out b	pasic				cing fa	actors	or pa	cking	densitie	es for B.C.C
						conc						1	0	1	y - I -	8		(08 Marks)
ł	).	Diff	eren	tiate	bet	ween	edge	anc	d scre	w di	slocat	ions	with	sketch	ies.			(08 Marks)
							No.	y					177	y				
	ι.	Wit	n the	hal	n 0:	fona	nt oo	muo	ntion		OR	atno	n dia	~ ***	av 1 a	.i., 41	1 1	C '11
ι.		stee	ı uıc	der	stat	ic uni	at co axial	tei	nsion	ai Su till f	ractur	Sua	in dia	gram,	expia	iin ine	benavi	our of mild (06 Marks)
)													terials	(i · 2	Conn	er ii	) Cast	iron
				A							. Y	5 ****		)	Сорр	01 11	) Cust	(02 Marks)
						twin			_	4 8	4							(06 Marks)
	l.	Defi	ne:	1) ł	Resi	lience	2 11	i) I	Ducti	ity.				4	Y			(02 Marks)
										Ma	dule-	2	1					
1	ι.	Witl	ı the	helr	of	neat s	sketc	hes	expl	ain tl	ne dif	<u>≠</u> feren	t stag	es of	ductile	e cum	and con	e fracture.
							(State					174				192		(08 Marks)
		Defi	ne C	reep	). W	ith a	typic	al c	reep	curve	e, expl	ain t	he di	fferen	t stage	es of c	reep.	(08 Marks)
						4	dir.					Tipe I			1			
		Who	ot ic	Fatio	nia <sup>c</sup>	Drov	v one	d own	nloin		OR N cui	*****	for .		7			(00 % // )
1.						at dis						ves	101 .					(08 Marks)
											gue li	mit.	. 1	4				
	).										tigue s		gth? I	Expla	in.			(08 Marks)
				77									Z.					
		D (		1.1	-		•				dule-							
		Den	ne S	olid	SOI	utions	and	exp	lain (	differ	ent ty	pes (	of soli	id sol	utions	with	figures.	(08 Marks)
	).	nucl	Ialli ei	me	поп	noger	ieous	s nu	icieai	ion.	Disci	iss t	ne si	gnine	ance	oi cri	tical ra	dius of the
	4	Huci	CI.			A					₽ Y							(08 Marks)
					/4h	All The Alle	n				OR							
1						ample				phase	e rule			Lever	rule.			(12 Marks)
	).										t sket		, expl	ain				
		i) ]	Eute	etic 1	reac	tion	ii	i) \ ]	Eutec	toid	reacti	on.						(04 Marks)
							4		p <sup>p</sup>									

Module-4

a. Explain the construction of TTT diagram, with figure and label it.
b. Write a short note on the following heat treatment processes:
i) Annealing ii) Carburizing. (08 Marks)

(08 Marks)

**OR** 

8 a. Give the composition and uses of various cast – irons.
b. Write a note on Aluminum alloys.

(08 Marks)

(08 Marks)

(08 Marks)

Module-5

9 a. Define Composite materials. Explain the role of matrix material in a composite.
b. What are the advantages and limitations of composite materials?
(06 Marks)

c. With a neat sketch, explain any one method for production of fibre reinforced plastic.

(06 Marks)

## OR

a. What are shape memory alloys? With a neat sketch, explain the stress – strain characteristics of SMA's as a function of temperature. (08 Marks)
b. What are the biological applications of smart materials used as implants? (04 Marks)
c. Write a note on use of non – destructive testing. (04 Marks)