CBCS SCHEME

WE TO	USN			477	18MT32
	4"16"IE		Third Samastar P. F. Dogr	on Evamination Jan	/Eab 2022
Third Semester B.E. Degree Examination, Jan./Feb. 2023 Material Science and Technology					
135	a was set		Material Science	te and recimoro	99
	Tim	e: 3 h	·s.		Max. Marks: 100
		7			
ice.		Note	: Answer any FIVE full questions, o	choosing ONE full question	from each module.
ompulsorily draw diagonal cross lines on the remaining blank pages. appeal to evaluator and /or equations written eg, $42+8=50$, will be treated as malpractice.			M	odule-1	
malj	1		xplain with neat diagram, plastic defe		g. (12 Marks)
sq as			xplain following with necessary grap Stiffness	hs where necessary:	
reate		,	Resilience		
ages.		iii	Toughness (A. A.	
nk pë I, wil		iv) Elasticity	And the second	(08 Marks)
5 blau = 50			A B ST	OR	
ining 2+8	2	a. St	ate Fick's two laws of diffusion. Lis-	t and explain how different f	factors affect diffusion?
rema eg, 4		1 P.			(10 Marks)
the itten			xplain with a neat diagram, fatigue to mple S-N curve.	est and explain now to draw	S-N curve from it. Draw a (10 Marks)
compulsorily draw diagonal cross lines on the remaining blank pages. , appeal to evaluator and /or equations written eg, $42+8=50$, will be 1		54	imple 8 1 curve.		(10 Marks)
s lination				lodule-2	
cros	3		ow would you construct TTT diagram		(10 Marks)
gonal Id /or			xplain full annealing for hypo and plications.	hyper eutectoid steer with	(07 Marks)
diag or an			hat factors affect the formation of	f martensite structure of th	
draw aluat		pı	ocess.		(03 Marks)
nily o				OR	
pulsc peal t	4	a. E	xplain Al-Cu alloys with composition		s. (06 Marks)
2 5			numerate Brasses and its types with		
vers,		c. W	hat is carburizing? What are the type	es of it? Explain pack carbur	nzing with diagram. (06 Marks)
On completing your answers, or Any revealing of identification		1			(OU HAMANS)
your	_	\ \bar{\bar{\bar{\bar{\bar{\bar{\bar{		lodule-3	1
ting ing o	5		erive an equation for net energy classifier state its significance.	lange for critical radius in	nomogeneous nucleation. (10 Marks)
mple			ompare Homogenous and Heterogen	eous nucleation.	(05 Marks)
n co ny re		c. E	xplain briefly the types of Solid Solu	tions.	(05 Marks)
1. O 2. A				OR	
important Note: 1. On completing your answers, 2. Any revealing of identification	6	a. E	xplain briefly the rules governing for		d solution. (05 Marks)
unt N		b. W	ith a neat phase diagram label ar		ases of Fe-C equilibrium
porta			agram.		(10 Marks)
lm		c. E	xplain Gibb's Phase Rule.		(05 Marks)

Module-4

Define Composite materials. What are the roles of its constituents in a composite? (10 Marks) 7

With the help of a neat diagram, explain the process parameters in Liquid Injection Molding process. State its advantages and disadvantages.

OR

List and explain the types of reinforcement materials. 8

(06 Marks)

What are the types of MMCs and explain them in brief. b.

(06 Marks)

What are the applications of composite materials?

(08 Marks)

Module-5

Explain with a neat diagram, how a piezoelectric material can be used as a transducer.

(06 Marks)

What is pseudo-elasticity with respect to shape memory alloys and explain shape memory

(08 Marks) (06 Marks)

effect with an example. Explain magnetorheological fluids.

Write a short note on: 10

Accelerometers

Load Cells b.

Microphones c.

Fiber-optic sensor

(20 Marks)