	 	_	 _			S14.01	
USN							15MA52


# Fifth Semester B.E. Degree Examination, Dec.2018/Jan.2019

		Fitti Semester B.E. Degree Examination, Dec.2018/Jan.201	9
		Computer Aided Design and Manufacturing	
Tir	ne.	3 hrs.	larks: 80
1 11	110	iviax. Ivi	iarks: 80
	Λ	ote: Answer any FIVE full questions, choosing ONE full question from each mo	dule.
		Module-1	
1	a.	Define and explain briefly CAD/CAM.	(0.4.3% )
	b.	With a neat block diagram, explain the product cycle overlaid with CAD/CAM.	(04 Marks) (12 Marks)
		a read of the analysis of plant the product cycle overlaid with CAD/CANI.	(12 Marks)
		OR	
2	a.	Explain the application of computers to the design process with block diagram.	(12 Marks)
	b.	Enumerate the advantages of CAD/CAM (any 8).	(04 Marks)
		Module-2	
		<u>wiodule-2</u>	
3	a.	Explain with neat diagram the cathode ray tube. To generate the images on C	RT screen.
		explain the techniques used in computer graphics.	(11 Marks)
	b.	List out the detailed classification of the input and output devices.	(05 Marks)
4	a.	OR Explain briefly the function of a Graphics package.	(0534 1)
•	b.	Illustrate the three transformations for two dimension considering a line.	(05 Marks) (07 Marks)
	c.	Explain briefly the basic features of IGES and STEP to exchange of modeling dat	a.
			(04 Marks)
		Module-3	
5	a.	Explain the basic steps of Finite Element Method (FEM).	(08 Marks)
	b.	Sketch the different types of 1D, 2D and 3D elements (any eight).	(08 Marks)
	J		()
		OR	
6	a.	Explain the three NC motion control systems.	(06 Marks)
	b. c.	Explain how ATC works in a machining centers with neat sketch.  Compare CNC and DNC (any four).	(06 Marks)
	C.	Compare Cive and Dive (any lour).	(04 Marks)
		Module-4	
		And the second s	

- Explain the different NC words.
  Explain the following:
  (i) CNC Machining center
  (ii) CNC Turning center. (08 Marks)
  - - (08 Marks)

## OR

- 8 a. Explain the part programmer's and computer job in computer assisted part programming.
  (06 Marks)
  - b. Write the manual part programming of the part shown in Fig.Q8(b). Assume suitable feed and speed rate. The thickness of the component is 5 mm. Milling tool φ10 mm. (12 Marks)



## Module-5

- 9 a. Define Robot. Enumerate the different configurations of robot. Explain with neat sketch any two types of configurations. (08 Marks)
  - b. Explain briefly the four programming methods of robot.

(08 Marks)

### OR

- 10 Write short notes (any four) of the following:
  - (i) End effectors
  - (ii) Robot sensors
  - (iii) Robot applications.
  - (iv) Robot motions
  - (v) Work cell control and interlocks.

(16 Marks)