

18ME46B/18MEB406

Fourth Semester B.E. Degree Examination, June/July 2023 **Mechanical Measurements and Metrology**

Time: 3 hrs.

Max. Marks: 100

| | N | Note: Answer any FIVE full questions, choosing ONE full question from each mo | odule. |
|---|------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| | | | |
| | | Module-1 | |
| 1 | a. | Define Metrology. State the objectives of Metrology. | (05 Marks) |
| | b. | Discuss with a neat sketch of International proto type meter. | (08 Marks) |
| | C. | Define Standard in Measurement. How are the standards classified? Explain with | example. |
| | | | (07 Marks) |
| | | O.D. | |
| 2 | a. | OR Identify different parts of sine center and symbols by the second symbols by the sec | HART SELE |
| ~ | b. | Identify different parts of sine center and explain how taper angles are measured. Describe the steps in wringing of slip gauges. | |
| | c. | Build the following dimensions using M – 87 set: | (04 Marks) |
| | ٠. | i) 49.3825mm ii) 87.3215mm. | (00 7 7 7) |
| | | 1) 19.3502311111 | (08 Marks) |
| | | Module-2 | |
| 3 | a. | Distinguish between Interchangeability and Selective assembly. | (06 Marks) |
| | b. | Discuss 'Hole based' and 'Shaft based' system of fits with sketches. | (08 Marks) |
| | C. | State and explain Taylor's principle of gauge design. | (06 Marks) |
| | | | (001.141115) |
| | | OR | |
| 4 | a. | Mention important functional requirements of a comparators. | (05 Marks) |
| | b. | With a neat sketch, explain the construction and working of Johanson's Mikrokato | or. |
| | c. | What is I VDT? With a diagram arribin the Overtile in the Country | (07 Marks) |
| | О. | What is LVDT? With a diagram, explain the Operating principle / working and ap of LVDT. | |
| | | OLEV DI. | (08 Marks) |
| | | Module-3 | |
| 5 | a. | Explain Terminology of screw thread. | (04 Maules) |
| | b. | How do you find effective diameter of a screw thread using Two – Wire method? | (04 Marks) (08 Marks) |
| | C. | Explain Tool Maker's Microscope with a neat sketch. Give its applications. | (08 Marks) |
| | X | The state of the s | (00 Marks) |
| | | OR | |
| 6 | a. | Illustrate the construction and working of co-ordinate measuring machine. | (10 Marks) |
| | b. | Explain Constant Chord Method of Tooth thickness measurement of gear. | (10 Marks) |
| | | 1 | |
| _ | 5020 | Module-4 | |
| 7 | a. | With the aid of a block diagram, explain the three stages of a generalized me | asurement |
| | h | Discourse all the first terms of | (10 Marks) |
| | b. | Discuss the terms with relevant sketches: i) Accuracy ii) Precision iii) Linearity iv) Calibration v) Threshold | |
| | | iii) Linearity iv) Calibration v) Threshold. | (10 Marks) |

OR

18ME46B/18MEB406

- 8 a. Mention any five Mechanical and five Electrical transducers. (05 Marks)
 - b. Describe in detail a ballast circuit. (07 Marks)
 - c. What are X Y plotters? With block diagram, explain working of X Y plotters. (08 Marks)

Module-5

- 9 a. Discuss the working of McLeod gauge. (10 Marks)
 - b. Explain the working of Prony brake dynamometer. (10 Marks)

OR

- 10 a. Summarize the laws of Thermocouple and Resistance Thermo meter with sketch. (10 Marks)
 - b. Define Gauge factor of a strain gauge and explain with a neat sketch, measurement of strain using wheat stone bridge circuit. (10 Marks)